

PRODUCT CHANGE NOTIFICATION (PCN)

Product Category CABINETS AND THERMALS 20210324-2

Product Group CONVERGED INFRASTRUCTURE

ISSUE DATE: 20210324

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Discontinuation of some Cabinets and Thermal products.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2021	4	5

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Compatibility Type	Replacement Part 1
BVXBFDBLED7	No Replacement	NO-REPLACEMENT
BVXBFDBLED7W	No Replacement	NO-REPLACEMENT
BVXRFBLED7	No Replacement	NO-REPLACEMENT
BVXRFBLED7W	No Replacement	NO-REPLACEMENT
CID2RU16-20QSAB	No Replacement	NO-REPLACEMENT
CQSVNX26A79	No Replacement	NO-REPLACEMENT
DELFBLED7W	No Replacement	NO-REPLACEMENT
G3-S6512B	No Replacement	NO-REPLACEMENT
G3-S6822B	No Replacement	NO-REPLACEMENT
G3-S7229B	No Replacement	NO-REPLACEMENT
G3-S7522B	No Replacement	NO-REPLACEMENT
G3-S8222B	No Replacement	NO-REPLACEMENT
G3-S8812B	No Replacement	NO-REPLACEMENT
N8212BXZ1	No Replacement	NO-REPLACEMENT
N8212BXZ3	No Replacement	NO-REPLACEMENT
N8212BXZ4	No Replacement	NO-REPLACEMENT
N8219BXZ1	No Replacement	NO-REPLACEMENT
N8219BXZ3	No Replacement	NO-REPLACEMENT
N8219BXZ4	No Replacement	NO-REPLACEMENT
N8222BXZ1	No Replacement	NO-REPLACEMENT
N8222BXZ2	No Replacement	NO-REPLACEMENT
N8222BXZ4	No Replacement	NO-REPLACEMENT
N8229BXZ1	No Replacement	NO-REPLACEMENT
N8229BXZ2	No Replacement	NO-REPLACEMENT
N8229BXZ4	No Replacement	NO-REPLACEMENT
N8229BXZ5	No Replacement	NO-REPLACEMENT
N8512BXZ1	No Replacement	NO-REPLACEMENT
N8512BXZ2	No Replacement	NO-REPLACEMENT
N8512BXZ4	No Replacement	NO-REPLACEMENT
N8519BXZ1	No Replacement	NO-REPLACEMENT
N8519BXZ2	No Replacement	NO-REPLACEMENT
N8519BXZ4	No Replacement	NO-REPLACEMENT
N8519BXZ5	No Replacement	NO-REPLACEMENT
N8522BXZ2	No Replacement	NO-REPLACEMENT
N8522BXZ4	No Replacement	NO-REPLACEMENT
N8522BXZ5	No Replacement	NO-REPLACEMENT
N8529BXZ2	No Replacement	NO-REPLACEMENT
N8529BXZ3	No Replacement	NO-REPLACEMENT
N8529BXZ5	No Replacement	NO-REPLACEMENT
N8812BXZ2	No Replacement	NO-REPLACEMENT
N8812BXZ3	No Replacement	NO-REPLACEMENT
N8812BXZ5	No Replacement	NO-REPLACEMENT
N8819BXZ1	No Replacement	NO-REPLACEMENT
N8819BXZ3	No Replacement	NO-REPLACEMENT
N8819BXZ5	No Replacement	NO-REPLACEMENT
N8822BXZ1	No Replacement	NO-REPLACEMENT

N8822BXZ3	No Replacement	NO-REPLACEMENT
N8822BXZ4	No Replacement	NO-REPLACEMENT
N8829BXZ1	No Replacement	NO-REPLACEMENT
N8829BXZ3	No Replacement	NO-REPLACEMENT
N8829BXZ4	No Replacement	NO-REPLACEMENT
S2EOR1BA1070W1	No Replacement	NO-REPLACEMENT
S8229DLM	No Replacement	NO-REPLACEMENT
S8229DLMW	No Replacement	NO-REPLACEMENT
SN7VCMG	No Replacement	NO-REPLACEMENT
STDH2-KIT	No Replacement	NO-REPLACEMENT
S8229DLM	No Replacement	NO-REPLACEMENT
S8229DLMW	No Replacement	NO-REPLACEMENT
STDH2-KIT	No Replacement	NO-REPLACEMENT
C12V305MV-8048	No Replacement	NO-REPLACEMENT
CQSVNX24A79	No Replacement	NO-REPLACEMENT
CQSVNX24B79	No Replacement	NO-REPLACEMENT
CQSVNX26B79	No Replacement	NO-REPLACEMENT
G3-S6212B	No Replacement	NO-REPLACEMENT
G3-S7212B	No Replacement	NO-REPLACEMENT
G3-S7822B	No Replacement	NO-REPLACEMENT
G3-S8522B	No Replacement	NO-REPLACEMENT
N8212BXZ2	No Replacement	NO-REPLACEMENT
N8212BXZ5	No Replacement	NO-REPLACEMENT
N8219BXZ2	No Replacement	NO-REPLACEMENT
N8219BXZ5	No Replacement	NO-REPLACEMENT
N8222BXZ3	No Replacement	NO-REPLACEMENT
N8222BXZ5	No Replacement	NO-REPLACEMENT
N8229BXZ3	No Replacement	NO-REPLACEMENT
N8229WPPABTAN19	No Replacement	NO-REPLACEMENT
N8512BXZ3	No Replacement	NO-REPLACEMENT
N8512BXZ5	No Replacement	NO-REPLACEMENT
N8519BXZ3	No Replacement	NO-REPLACEMENT
N8522BXZ1	No Replacement	NO-REPLACEMENT
N8522BXZ3	No Replacement	NO-REPLACEMENT
N8529BXZ1	No Replacement	NO-REPLACEMENT
N8529BXZ4	No Replacement	NO-REPLACEMENT
N8812BXZ1	No Replacement	NO-REPLACEMENT
N8812BXZ4	No Replacement	NO-REPLACEMENT
N8819BXZ2	No Replacement	NO-REPLACEMENT
N8819BXZ4	No Replacement	NO-REPLACEMENT
N8822BXZ2	No Replacement	NO-REPLACEMENT
N8822BXZ5	No Replacement	NO-REPLACEMENT
N8829BXZ2	No Replacement	NO-REPLACEMENT
N8829BXZ5	No Replacement	NO-REPLACEMENT

